

Items Needed

- One USB thumb drive
- firmware.bin.uap file
- gw3mm.xxx.bin file
- gw3mm.xxx.sh1 file
- Place all 3 firmware files on the USB thumb drive in the root directory

Update the Connect

- Flip all four dipswitches on the Connect down
- Plug the Connect into power
- The green LED will turn on and off
- Wait 30 seconds
- Plug the thumb drive into the Connect
- The red LED will come on (may take up to 30 seconds)
- The green LED will come on along with the red LED
- The red LED will go off and the green LED will stay on
- Updating the connect is complete
- Unplug the thumb drive
- Unplug the Connect
- Flip all four dipswitches back up